

REPLACEMENT FOR

BUICK CENTURY '99 CHINA TYPE

132-1101-LD

HEAD LAMP
R 92682
L 92683
PCS CFT



H1/H1/P21W/P21W/W5W

TBA

REPLACEMENT FOR

BUICK CENTURY '03 CHINA TYPE

132-1104-LD

HEAD LAMP
R
L
PCS CFT



H1/H7/W5W

TBA

REPLACEMENT FOR

BUICK GL8 '94 CHINA TYPE

132-1103-LD

HEAD LAMP
R
L 16530511
PCS CFT



H4/W5W

TBA

BUICK

132-2001

FOR LAMP
R 10292680
L 10292681
PCS CFT



H3

TBA

'97

132-2002

FOR LAMP
R
L
PCS CFT



H3

TBA

132-1103-LDH

HEAD LAMP
R
L
PCS CFT



H4/W5W

TBA

132-1901

TAIL LAMP
R
L
PCS CFT



TBA

'2000

442-1402N-C

SIDE LAMP
100PCS 0.90CFT



WY5W

132-1501-U

CORNER LAMP
R
L 16530275
PCS CFT



PY21W

TBA

132-1903

TAIL LAMP
R
L
PCS CFT



P21W/P21/5W/W5W

TBA

132-1902

TAIL LAMP
R
L
10PCS CFT



TBA


REPLACEMENT FOR

BUICK GL8 '99
CHINA TYPE

BUICK

132-1102-LD
HEAD LAMP
R
L
PCS CFT

H4/PY21W/W5W **TBA**



132-1902
TAIL LAMP
R
L
10PCS CFT

TBA

